

**State of Wisconsin - Department of Natural Resources
Substance Release Notification Report
Report created on 04/08/2008**

SPILL ID# 20080314NE31-1

BRRTS# 04-31-551304

04-31 551304

Incident Date & Time: 03/14/2008 10:00	Reported Date & Time: 03/14/2008 13:03	BRRTS No: 04-31-551304	Spill ID: 20080314NE31-1
DATCP Reported? No DATCP Transferred? No	NFA Letter Sent? No	ERP Transferred? No	Incident Closed? Yes : 03/24/2008

Location			
Region: NE	County: Kewaunee	Municipality: LINCOLN, TOWNSHIP OF	
Facility/Property Name and Street Address: DAIRY DREAM LLC E 3576 CARDINAL ROAD		Description: MANURE HOLDING AREA - SOUTH OF BARN	
Facility Type: Farm/Farm Field (private and corporate, tree nursery)			
Lat/Long: 44° 39' 710" , 87° 35' 405"	PLSS: SE ¼ of SE ¼ of Sec 4, T25N, R24E	WTM:	
Weather Conditions: Sunny			

Responsible Parties			
Name/Address (1): DAIRY DREAM LLC E 3576 CARDINAL ROAD CASCO , WI 54205- (920) 621-3253 x Primary (920) 837-2777 x Secondary	Contact: DON NILES MANAGING PARTNER (920) 621-3253 x primary	Other Contact:	Spill Packet:

Cause
THIS DAIRY FARM HAS A RECYCLING PUMP SYSTEM. THE FIRST PUMP, PUMPS LIQUID MANURE FROM THE HOLDING AREA UNDERGROUND TO THE SETTLING PIT. THE SECOND PUMP THEN PUMPS CLEANER MANURE WATER BACK TO THE HOLDING AREA. THE CLEANER MANURE WATER IS USED TO CLEAN THE SAND USED FOR CATTLE BEDDING. THE FIRST PUMP FAILED WHEN THE PUMP MOTOR STOPPED WORKING. AS A RESULT THE SECOND PUMP CONTINUED TO PUMP CLEANER MANURE WATER BACK INTO THE HOLDING AREA CAUSING AN OVER FLOW.

Cause Type: Manure Release (pit, line break, transportation, field application)

Substances						
Name	Other / Comments	Amt Released	Amt Recovered	Type	Color	Odor
Manure		50000.0 Gal	50000.0 Gal	LIQUID		

Environmental Impacts / Damages			
Environmental Impacts: CONCRETE CONTAINED	Resource Damages: No	Injuries: No	Evacuation: No


Cleanup Actions	
Method	Description
Other	PUMPS

Cleanup Action Comments
DELEBRUIX CUSTOM HAULERS WAS HIRED TO PUMP THE MANURE WHICH WAS CONTAINED IN THE CONCRETE HOLDING AREA BACK INTO THE MANURE PIT. DART ELECTRIC WAS HIRED TO REPLACE THE FAILED PUMP MOTOR. THE SECOND PUMP THAT CAUSED THE THE OVER FLOW WAS SHUT OFF UNTIL THE FAILED PUMP MOTOR CAN BE REPLACED TO PREVENT CONTINUED OVER FLOW.

Contractors Hired	
Name	Description
OTHER	PUMP EQUIPMENT

State of Wisconsin - Department of Natural Resources
Substance Release Notification Report
Report created on 04/08/2008

SPILL ID# 20080314NE31-1
BRTS#04-31-551304

Waste Destinations				
Location		Description		
ON SITE		MANURE PIT		
Agencies Notified / On Scene				
Agency		Notified	On Scene	
DNR		X	X	
LEPC OF LOCAL EMERG MGT		X		
LAND CONSERVATION OFFICE		X		
Additional Comments				
<p>ON FRIDAY, MARCH 14, 2008, AT ABOUT 11:53AM WARDEN KUHN RECEIVED A REPORT OF A MANURE RELEASE AT THE DAIRY DREAMS DAIRY FARM LOCATED AT E3576 CARDINAL ROAD, IN THE TOWN OF LINCOLN, KEWAUNEE COUNTY, WI. WARDEN KUHN WAS ADVISED BY THE HOTLINE STAFF THAT THE MANURE WAS CONTAINED AND CLEANUP WAS UNDER WAY. AT ABOUT 1:30PM WARDEN KUHN ARRIVED ON SCENE AND MET WITH THE RP (DON NILES). NILES EXPLAINED THAT THE MANURE AND SAND BEDDING IS SCRAPED FROM THE BARN AND INTO A CONCRETE HOLDING CANAL. THE LIQUID MANURE FLOWS DOWN THE CANAL INTO A CONCRETE HOLDING AREA. THE SAND BEDDING SETTLES OUT IN THE CANAL. ONCE THE LIQUID MANURE IN THE HOLDING AREA REACHES A DESIGNATED HEIGHT THE LIQUID MANURE IS PUMPED UNDER GROUND TO A MANURE PIT. THE SOLIDS SETTLE OUT IN THE FIRST MANURE PIT. THE LIQUID THEN FLOWS INTO A SECONDARY MANURE PIT. THE CLEANER MANURE WATER IS THEN PUMPED BACK INTO THE HOLDING AREA AND CANAL TO WASH OUT THE BEDDING SAND. THE RELEASE RESULTED AFTER THE PUMP THAT PUMPS THE MANURE FROM THE HOLDING AREA INTO THE FIRST SETTLING PIT FAILED. THE SECOND PUMP CONTINUED TO PUMP CLEANER MANURE WATER BACK INTO THE HOLDING AREA AND CANAL. WITH ONE HALF OF THE RECYCLING SYSTEM FAILING CAUSED THE HOLDING AREA TO OVER FLOW. NILES EXPLAINED THAT ONCE THE PROBLEM WAS DISCOVERED THE SECOND PUMP WAS TURNED OFF TO PREVENT ANY ADDITIONAL RELEASE. THE HOLDING AREA WAS BEING PUMPED DOWN USING EXTERNAL PUMPING EQUIPMENT AND LARGE DIAMETER HOSE. THE MANURE THAT WAS BEING PUMPED OUT OF THE HOLDING AREA WAS BEING PUMPED BACK INTO THE MANURE PIT. ONCE THE MANURE HOLDING AREA WAS DOWN THE FAILED PUMP WAS GOING TO BE REPAIRED. A SMALL AMOUNT OF MANURE OVER TOPPED THE HOLDING AREA ONTO THE GROUND EAST OF THE HOLDING AREA. THIS AREA WAS ABOUT 100 FEET LONG, 6 FEET WIDE AND ABOUT 6 INCHES DEEP. THIS MANURE WAS UP HILL FROM THE CONCRETE STORAGE AREA AND WITH CONTINUED MELTING WOULD WASH THIS MANURE BACK INTO THE HOLDING AREA. THE MANURE THAT WAS OUTSIDE THE HOLDING AREA WAS NOT A THREAT TO ANY SURFACE WATERS AND DID NOT POSE ANY ENVIRONMENTAL PROBLEMS. NILES WAS ADVISED TO WASH THE AREA EAST OF THE HOLDING AREA TO GET THE MANURE BACK INTO THE HOLDING AREA. THIS SPILL WAS ALL CONTAINED AND UNDER CONTROL PRIOR TO WARDEN KUHN'S ARRIVAL.</p>				
Enforcement Actions				
Enforcement action? No				
Case Activity Report Numbers:		(1)		
Person Reporting				
Name	Representing / Address	Primary Phone	Secondary Phone	
DON NILES	DAIRY DREAM	(920) 621-3253 x	(920) 837-2777 x	
Contractors Hired				
Name / Address			Zone Contractor Hired by DNR?	
			No	
Contacts				
Role	Name / Address	Office Phone	Date	Time
Prepared By:	DARREN KUHN	(920) 845-9079 x	03/14/2008	
Person Notified:	WARDEN DARREN KUHN		03/14/2008	1330
Investigated By:	DARREN KUHN	(920) 845-9079 x	03/14/2008	1153
Incident Commander:				
Spill Coordinator:	NE - MOELLER, JASON [P] 920-662-5492		03/24/2008	1153
Electronic Attachments (list)				
Name		Type		